DATE: 11/13/04 (UPDATED 11/30/05)
SUBJECT: DATA DISPLAY FORMAT GUIDELINES FOR MACHINES
FROM : T.GLASER
TO: H.SADA

PLEASE USE THIS FORMAT FOR MACHINE DISPLAYS

		EXAMPLE
OHMS	X.XX	2.31
VOLTS	X.X	12.1
AMPS	X.X	11.9
mA	X.X	82.8
ACTUATOR POSITION	X.X OR X.XX*	124.4
CYLINDER POSITION	X.X	23.9
AIR FLOW	X.	1756
RPM	X.	3543
TIME (MIN)	X.XXX	0.724
TIME (SEC X 1000)	X.	43440
TIME (SEC)	X.XX	43.44

*ALSO AS NEW UNITS OF MEASUREMENT ARE REQUIRED PLEASE ONLY DISPLAY SIGNIFICANT I
THANK YOU

DIGITS