4/4/0000 LIDD ATED 5/45/07				
1/4/2006 UPDATED 5/15/07				
PASS - FAIL BIN LOGIC				
T.GLASER				
TRUTH TABLE				
		PASS SENSOR INTERRUPTED	FAIL SENSOR INTERRUPTED	NO SENSOR
				INTERRUPTED
PASSED UNIT	OUT OF FIXTURE	OK	SUPERVISOR RESET	OK
FAILED UNIT	OUT OF FIXTURE	SUPERVISOR RESET	OK	WAIT FOR SENSOR
				TO BE INTERRUPTED
PASSED UNIT	IN FIXTURE	SUPERVISOR RESET	SUPERVISOR RESET	OK
FAILED UNIT	IN FIXTURE	SUPERVISOR RESET	SUPERVISOR RESET	OK
UNKNOWN ORIGIN		SUPERVISOR RESET	SUPERVISOR RESET	OK